


EXISTING CONDITIONS AT
105 ASCOT DR. ROSEVILLE, CA



North Elevation, East half, Existing Laundry on left



North Elevation, West half, empty hair salon on right



West Elevation



South Elevation, Block wall on property line



Northeast Corner



East Wall with utility services